

2/2



ROSE ISLE, FOREST.

MAY 1932. compartment 40.

Building of artificial dunes with
brushwood barriers. Incorrect type of dune
(face too steep thus:- $\cap$) caused by a too
close mesh barrier left too long in position
This was erected by previous owners prior to
acquisition by Forestry Commission